

Date of Issue : 2026 – 08 – 11

Mechanical Properties

Chemical Composition (%)

Others

* Q'ty: 600 kg

We hereby certify that the material covered by this report has been inspected in accordance with and been found to meet the applicable requirements of specification and customer's requirements.

Approved by

Chapman

QA Manager Pham Dinh Anh Vu

HYUNDAI WELDING VINA CO., LTD.

Road N2, Nhon Trach 5 IZ, Nhon Trach Ward, Dong Nai City, Vietnam.